

drive shaft to the form shown on the right is vital on stroked, big bore engines so it clears the crank. However, reducing the shaft thickness on any engine seems to increase distributor bearing life and allows the distributor to hold the dwell angle longer.